



7th Generation Intel[®] Processor I/O for U/Y Platforms

Specification Update

***Supporting 7th Generation Intel[®] Core[™] Processor Family I/O
based on U/Y-Processor Platforms***

Revision 007

November 2024



You may not use or facilitate the use of this document in connection with any infringement or other legal analysis. You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

All product plans and roadmaps are subject to change without notice.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration. No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

© Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries.

*Other names and brands may be claimed as the property of others.

Copyright © 2016-2024, Intel Corporation. All rights reserved.

Contents

Preface	5
Summary Tables of Changes	6
Errata Details	11
Specification Changes	25
Specification Clarification	26
Document-Only Change.....	27



Revision History

Revision Number	Description	Revision Date
001	• Initial Release	August 2016
002	• Added support for 8th Generation Intel® Processor Family I/O for U Quad Core Platforms	August 2017
003	• Added Errata: 30 to 41	February 2019
004	• Added Errata: 42	March 2019
005	• Added Erratum: 43 to 45 • Updated Errata: 20 and 41	January 2020
006	• Added Specification Clarification 1	November 2021
007	• Added Erratum: 46 .	November 2024

§§

Preface

This document is an update to the specifications contained in the Affected Documents table below. This document is a compilation of device and documentation errata and specification changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in Nomenclature are consolidated into the specification update and are no longer published in other documents.

This document may also contain information that was not previously published.

Affected Documents

Document Title	Document Number
7th Generation Intel® Processor I/O for U/Y Platforms Datasheet – Volume 1 of 2	334658
7th Generation Intel® Processor I/O for U/Y Platforms Datasheet – Volume 2 of 2	334659

Nomenclature

Errata are design defects or errors. Errata may cause the behavior of the PCH to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present in all devices.

Specification Changes are modifications to the current published specifications. These changes are incorporated in any new release of the specification.

Specification Clarifications describe a specification in greater detail or further highlight a specification’s impact to a complex design situation. These clarifications are incorporated in any new release of the specification.

Documentation Changes include typos, errors, or omissions from the current published specifications. These are incorporated in any new release of the specification.

Note: Errata remain in the specification update throughout the product’s life cycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, and so on).



Summary Tables of Changes

The following tables indicate the errata, specification changes, specification clarifications, or documentation changes which apply to the product. Intel may fix some of the errata in a future stepping of the component and account for the other outstanding issues through documentation or specification changes as noted. These tables use the following notations:

Codes Used in Summary Table

Stepping	Description
X	Erratum exists in the stepping indicated. Specification Change that applies to the stepping indicated.
(No mark) or (Blank Box)	This erratum is fixed or not applicable in listed stepping or Specification Change does not apply to listed stepping.

Status	Description
Doc	Document change or update that is implemented.
Planned Fix	This erratum may be fixed in a future stepping of the product.
Fixed	This erratum has been previously fixed.
No Fix	There are no plans to fix this erratum.

Errata Summary Table

Erratum Number	Stepping	Status	Errata
	C1		
1	X	No Fix	xHC Data Packet Header and Payload Mismatch Error Condition
2	X	No Fix	USB SuperSpeed Packet with Invalid Type Field Issue

Summary Tables of Changes

Erratum Number	Stepping	Status	Errata
	C1		
3	X	No Fix	xHC Behavior with Three Consecutive Failed U3 Entry Attempts
4	X	No Fix	Max Packet Size and Transfer Descriptor Length Mismatch
5	X	No Fix	xHCI Controller OC# Issue
6	X	No Fix	xHCI USB 2.0 Split-Transactions Error Counter Reset Issue
7	X	No Fix	USB xHCI Controller May Not Re-enter a D3 State After a USB Wake Event
8	X	No Fix	USB 3.0 Devices Not Detected After Sx Resume
9	X	No Fix	PCI Express Unexpected Completion Status Bit May Get Set
10	X	No Fix	eSPI Concurrent Get-Config and Flash Cycles
11	X	No Fix	xHCI U3 Wake Exit Issue
12	X	No Fix	xHCI Controller USB Debug Port Disconnect Issue
13	X	No Fix	PSIC Field Incorrect Value
14	X	No Fix	xHCI Extended Capabilities Registers are Incorrectly Implemented as Read/Write
15	X	No Fix	SPI Dual I/O and Quad I/O Modes
16	X	No Fix	eSPI Turn Around (TAR) Spec Violation
17	X	No Fix	SMBus Transaction Using Memory Mapped I/O Registers
18	X	No Fix	xHCI Host Controller USB 2.0 Control Transfer May Cause IN Data to be Dropped

Erratum Number	Stepping	Status	Errata
	C1		
19	X	No Fix	System May Hang While Restoring HSIO ModPHY Configuration
20	X	No Fix	xHCI Host Controller Reset May Cause a System Hang
21	X	No Fix	PCI Express* Gen2 x4 Device May Cause a Machine Check Exception
22	X	No Fix	PCH PCIe* Controller Root Port Access Control Services Control Registers (ACCTRL) Appear as Read Only
23	X	No Fix	Pull-up and Pull-down on SPI CS# and CLK Signals
24	X	No Fix	eSPI Error Reporting
25	X	No Fix	USB 3.0 DCI Control Packet Issue
26	X	No Fix	eSPI Fatal Error Handling
27	X	No Fix	PCH PCIe* TX Pin State During L1.0 and L1.1 Substates
28	X	No Fix	Subsequent Deep S5 and S5 Exits Impacted After "Straight to S5 (Host Stays There)" Resets
29	X	No Fix	eSPI Bus Mastering
30	X	No Fix	Voltage Floating on USB - Device Mode Capable Port
31	X	No Fix	USB 3.0 – Jitter Tolerance Margin
32	X	No Fix	Failure of USB compliance test TD 7.01 Link Bring-up Test (Subtests 1 and 2)
33	X	No Fix	Intermittent Failure of USB Compliance Test TD3.08
34	X	No Fix	Intel® RST for PCIe Storage - SATA PCI Configuration Read

Summary Tables of Changes

Erratum Number	Stepping	Status	Errata
	C1		
35	X	No Fix	xHCI Controller May Hang on D3 Entry Following a Hot-plug Event
36	X	No Fix	USB 2.0 PLL May Fail to Lock During S3 Resume
37	X	No Fix	PCIEXP_WAKE_STS Bit Not Set as Expected
38	X	No Fix	xHCI USB Hardware LPM Capability (HLC) Register Reset to the Default Value During D3-D0 Transition
39	X	No Fix	Intel® Serial I/O Controller DMA LLP 4 GB Boundary Alignment
40	X	No Fix	eMMC / SDXC / SDIO CRC Detection
41	X	No Fix	USB DbC Or Device Mode Port When Resuming from S3, S4, S5 Or G3 State
42	X	No Fix	PCIe Root Port CLKREQ# Asserted Low to Clock Active Timing
43	X	No Fix	xHCI USB 2.0 ISOCH Device Missed Service Interval
44	X	No Fix	xHCI Short Packet Event Using Non-Event Data TRB
45	X	No Fix	eSPI SBLCL Register Bit Not Cleared by PLTRST#
46	X	No Fix	I ² S Audio Channels Swapped With High Frame Polarity in Device Mode

Specification Changes

No.	Stepping	Specification Changes
	C1	
		None for this revision of this specification update.

Specification Clarifications

No.	Specification Clarifications
1	SX_EXIT_HOLDOFF# Not Functional with eSPI Enabled

Documentation Changes

No.	Documentation Changes
	None for this revision of this specification update.

§ §

Errata Details

1	xHC Data Packet Header and Payload Mismatch Error Condition
Problem	<p>If a SuperSpeed device sends a DPH (Data Packet Header) to the xHC with a data length field that specifies less data than is actually sent in the DPP (Data Packet Payload), the xHC accepts the packet instead of discarding the packet as invalid.</p> <p>NOTE: The USB 3.0 specification requires a device to send a DPP matching the amount of data specified by the DPH.</p>
Implication	<p>The amount of data specified in the DPH is accepted by the xHC and the remaining data is discarded and may result in anomalous system behavior.</p> <p>NOTE: This issue has only been observed in a synthetic test environment with a synthetic device.</p>
Workaround	None.
Status	No plan to fix.

2	USB SuperSpeed Packet with Invalid Type Field Issue
Problem	<p>If the encoding for the "type" field for a SuperSpeed packet is set to a reserved value and the encoding for the "subtype" field is set to "ACK", the xHC may accept the packet as a valid acknowledgment transaction packet instead of ignoring the packet.</p> <p>NOTE: The USB 3.0 specification requires that a device never set any defined fields to reserved values.</p>
Implication	<p>System implication is dependent on the misbehaving device and may result in anomalous system behavior.</p> <p>NOTE: This issue has only been observed in a synthetic test environment with a synthetic device.</p>
Workaround	None.
Status	No plan to fix.

3	xHC Behavior with Three Consecutive Failed U3 Entry Attempts
Problem	<p>The xHC does not transition to the SS.Inactive USB 3.0 LTSSM (Link Training and Status State Machine) state after a SuperSpeed device fails to enter U3 upon three consecutive attempts.</p> <p>NOTE: The USB 3.0 specification requires a SuperSpeed device to enter U3 when directed.</p>
Implication	The xHC continues to try to initiate U3. The implication is driver and operating system dependent.
Workaround	None.
Status	No plan to fix.

4	Max Packet Size and Transfer Descriptor Length Mismatch
Problem	<p>The xHC may incorrectly handle a request from a low-speed or full-speed device when all the following conditions are true:</p> <ul style="list-style-type: none"> • The sum of the packet fragments equals the length specified by the TD (Transfer Descriptor) • The TD length is less than the MPS (Max Packet Size) for the device • The last packet received in the transfer is "0" or babble bytes
Implication	The xHC halts the endpoint if all the above conditions are met. All functions associated with the endpoint stops functioning until the device is unplugged and reinserted.
Workaround	None.
Status	No plan to fix.

5	xHCI Controller OC# Issue
Problem	xHCI Host Controller Reset (HCRST) may not complete if a USB over-current event occurs while powering on or resuming from S5 or S4.
Implication	<p>Upon resume all xHCI Ports may become non-functional.</p> <p>NOTE: To recover xHCI port functionality requires the USB Device causing an overcurrent event to be removed and the system to be reset.</p>
Workaround	None.
Status	No plan to fix.

6	xHCI USB 2.0 Split-Transactions Error Counter Reset Issue
Problem	The xHCI controller may not reset its split transaction error counter if a high-speed USB hub propagates a mal-formed bit from a low-speed or full-speed USB device exhibiting non-USB specification compliant signal quality.
Implication	<p>Upon resume all xHCI Ports may become non-functional.</p> <p>NOTE: To recover xHCI port functionality requires the USB Device causing an overcurrent event to be removed and the system to be reset.</p>
Workaround	None.
Status	No plan to fix.

Errata Details

7	USB xHCI Controller May Not Re-enter a D3 State After a USB Wake Event
Problem	After processing a USB 3.0 wake event, the USB xHCI controller may not re-enter D3 state.
Implication	When the failure occurs, the system would not enter an Sx state.
Workaround	Software should clear bit 28 PME Enable (PME_EN) of PMCRTL[28]PWR_CNTL_STS-- Power management Control/Status Register (USB xHCI-D20:F0: Offset 74h) after the controller enters D0 state following an exit from D3. For Microsoft* Windows* 7, workaround is included in Intel® USB 3.0 eXtensible Host Controller Driver, version 4.0.0.23 or later. For Microsoft* Windows* 8.1, workaround is included in Intel® USB 3.0 Host Controller Adaptation Driver, version 1.0.0.27 or later. Intel has notified all major OSV's of this behavior so this workaround may be implemented as needed.
Status	No plan to fix.

8	USB 3.0 Devices Not Detected After Sx Resume
Problem	While the system is in S3/S4/S5 and a USB 3.0 device is disconnected and reconnected to a system, the Cold Attach Status (CAS) bit 24 of PORTSCNUSB3-xHCI USB3 Port N Status and Control Register may be overwritten.
Implication	The system may not detect USB 3.0 devices after wake from S3/S4/S5.
Workaround	Software should issue a warm port reset when the PORTSCNUSB3-xHCI USB3 Port N Status and Control Register Port Link State (PLS) bits 8:5 is 0x7h(Link is in Polling State) and the CAS bit is 0.For Microsoft* Windows 7, workaround is included in Intel® USB 3.0 eXtensible Host Controller Driver, version 4.0.0.23 or later. For Microsoft* Windows* 8.1, workaround is included in Intel® USB 3.0 Host Controller Adaptation Driver, version 1.0.0.27 or later. Intel has notified all major OSV's of this behavior so this workaround may be implemented as needed.
Status	No plan to fix.

9	PCI Express* Unexpected Completion Status Bit May Get Set
Problem	A PCI Express* Device replaying an Completion TLP may incorrectly cause an Unexpected Completion Error. NOTE: This has only been observed when a PCIe device causes frequent link corruptions and recovery events to occur.
Implication	Bit 16 Unexpected Completion Status (UC) may get set in the Uncorrectable Error Status (UES) Register (PCI Express*-D28:F0/F1/F2/F3/F4/F5:offset 104h).
Workaround	System Software may set bit 16 Unexpected Completion Mask (UC) in the Uncorrectable Error Mask (UEM) Register (PCI Express*-D28:F0/F1/F2/F3/F4/F5:Offset 108h).
Status	No plan to fix.

10	eSPI Concurrent Get-Config and Flash Cycles
Problem	When an eSPI Get_Config cycle occurs concurrently with a flash cycle, the eSPI controller may stop working NOTE: The issue has only been observed in a synthetic test environment only
Implication	System may hang
Workaround	None.
Status	No plan to fix.

11	xHCI U3 Wake Exit Issue
Problem	xHCI Controller does not send the LFPS wake handshake for the full 10ms and reattempts U3 wakeup prior to the minimum 100ms wait time following a tNoLFPSResponseTimeout. NOTE: USB 3.0 Specification Section 7.5.9.2 Exit from U3 specifies the port remains in U3 when the 10-ms LFPS handshake timer times out (tNoLFPSResponseTimeout). And 7.2.4.2.7 Low Power Link State Exit Flow specifies a minimum of 100-ms delay between attempts to re-initiate U3 wakeup again.
Implication	Implication is USB 3.0 SuperSpeed Device and OS / Host Driver dependent. NOTE: Intel has Only observed this in a Synthetic Test Environment.
Workaround	None.
Status	No plan to fix.

12	xHCI Controller USB Debug Port Disconnect Issue
Problem	USB 3.0 Debug Port may hang when removing USB debug device. NOTE: This issue has only been observed infrequently during USB debug connector unplug events.
Implication	The Port would not function and require a Platform Reset to recover.
Workaround	None Identified.
Status	No plan to fix.

13	PSIC Field Incorrect Value
Problem	PSIC (The Protocol Speed ID Count) field incorrectly reports a value of 3. PSIC should report 6 indicating SSIC support.
Implication	If software utilizes PSIC, it may incorrectly determine SSIC is not supported. Additionally xHCI CV TD 1.09 Protocol Speed ID Test fails. Intel has obtained a waiver for PSIC.
Workaround	It may be possible for a BIOS code change to workaround this erratum.
Status	No plan to fix.

Errata Details

14	xHCI Extended Capabilities Registers are Incorrectly Implemented as Read/Write
Problem	Bits [15:0] of xHCI Extended Capabilities CSR (Debug Capability Descriptor Parameters – XHCI_BAR, Offset 8740H) are incorrectly implemented as Read/Write, instead of Read-Only.
Implication	This erratum causes the USB-IF xHCI CV TD 1.05 Extended Capabilities Registers Tests to report a failure; Intel has obtained a waiver for TD1.05. Intel has not observed this erratum with any commercially available software.
Workaround	None.
Status	No plan to fix.

15	SPI Dual I/O and Quad I/O Modes
Problem	When the PCH SPI controller is in Quad I/O or Dual I/O mode and reads a flash device which uses "mode cycles" after the address phase to enable the flash device's special mode, the MISO, IO2, and IO3 signals is pulled high by the PCH while the device expects the signals to be low.
Implication	SPI transactions may fail resulting in possible system hang or failure during boot.
Workaround	A BIOS code change has been identified and may be implemented as a workaround for this erratum.
Status	No plan to fix.

16	eSPI Turn Around (TAR) Spec Violation
Problem	C During the Turn Around (TAR) window, the eSPI controller does not drive the data lines to logic '1' for the first clock as specified by the eSPI specification.
Implication	There are no known functional failures due to this issue.
Workaround	None.
Status	No plan to fix.

17	SMBus Transaction Using Memory Mapped I/O Registers
Problem	When using memory-mapped-I/O DATA register for a SMBus write transaction, data transmitted from the register for Byte Write, Block Write, or Send Byte operation with Packet Error Check (PEC) enabled may not match the data programmed by software.
Implication	The SMBus transaction may fail. Implication depends on the failing transaction.
Workaround	Platform software should use IO-mapped registers for SMBus transactions.
Status	No plan to fix.

18	xHCI Host Controller USB 2.0 Control Transfer May Cause IN Data to be Dropped
Problem	USB 2.0 Control Transfers may incorrectly clear a USB 2.0 flow control condition to a USB 2.0 IN endpoint resulting in the dropping of IN Data to the flow controlled endpoint. Exposure is sensitive to high volume of unrelated OUT transactions occurring on the xHCI Host controller.
Implication	USB 2.0 Device dependent and may result in anomalous USB 2.0 Device behavior. NOTE: Intel has only observed this with a single USB 2.0 Device which frequently used USB 2.0 Control Transfers during operation.
Workaround	None. A BIOS code change has been identified and may be implemented as a workaround to significantly minimize exposure to the occurrence of this erratum.
Status	No plan to fix.

19	System May Hang While Restoring HSIO ModPHY Configuration
Problem	While Power Management Controller (PMC) is restoring High Speed I/O (HSIO) Modular Physical Layer (ModPHY) configuration during resume from S3, S4, S5 or while performing a platform reset the PMC may hang if a PMC managed timer expires during this time period.
Implication	System may hang during resume.
Workaround	A BIOS code change has been identified and may be implemented as a workaround for this erratum.
Status	No plan to fix.

20	xHCI Host Controller Reset May Cause a System Hang
Problem	xHCI Host Controller may not respond following system software setting (Bit 1 = '1') the Host Controller Reset (HCRST) of the USB Command Register (xHCIBAR + 80h).
Implication	CATERR may occur resulting in a system hang.
Workaround	A BIOS code change has been identified and may be implemented as a workaround for this erratum.
Status	No plan to fix.

Errata Details

21	PCI Express* Gen2 x4 Device May Cause a Machine Check Exception
Problem	PCH PCI Express Host Controller when configured as Gen2 x4 may not properly handle an abrupt link transition to electrical idle without receiving Electrical Idle Ordered Set (EIOS) such as during hot unplug event.
Implication	Platform May Hang due to a Machine Check Exception if all of the following conditions are met when the link is terminated abruptly: <ul style="list-style-type: none"> • No 8b10b errors occur, • A TLP of exactly 3DWords is received (length started to count from STP as the first byte) <p>NOTE: A valid TLP length is 5DWords at least.</p> <ul style="list-style-type: none"> • The TLP must end with END or EDB, • And dependent on the specific internal timing of the DW alignment.
Workaround	None Identified.
Status	No plan to fix.

22	PCH PCIe* Controller Root Port Access Control Services Control Registers (ACSCTLR) Appear as Read Only
Problem	ACSCTLR is implemented and documented in the External Design Specification (EDS) at Offset 0x148 instead of at Offset 0x146 as documented in the PCI-SIG PCI Express® Base Specification
Implication	ACS aware software would not be able to access and configure ACSCTLR at Offset 0x146
Workaround	ACS aware software must account for and access ACSCTLR at Offset 0x148 as documented in the Datasheet.
Status	No plan to fix.

23	Pull-up and Pull-down on SPI CS# and CLK Signals
Problem	The pull up/pull down implementation before RSMRST# assertion on SPI chip select (CS#) and clock (CLK) signals does not match the specified behavior. The actual implementation has no pull-up or pull down before RSMRST# assertion.
Implication	System implication depends on the external device requirements sampling the SPI CS# and CLK signals.
Workaround	Implement an external pull-up, depending on the external device requirements.
Status	No plan to fix. The correct implementation information is updated in Revision 002 of the 6th Generation Intel Processor Families IO Platform Datasheet.

24	eSPI Error Reporting
Problem	When errors occur on the eSPI interface, the eSPI error reporting registers (VWERR_SLV, LNKERR_SLV, FCERR_SLV, PCERR_SLV, SLV_CFG_REG_CTL) may not be updated correctly.
Implication	Platform implication depends on the software usage of the registers.
Workaround	NOTE: eSPI error handling software may issue an in-band reset to the eSPI device when detecting an error associated with these registers.
Status	No plan to fix.

25	USB 3.0 DCI Control Packet Issue
Problem	DbC (Debug Capability) Device connection may hang if the USB 3.0 host controller DCI (Direct Connect Interface) does not send Control Packets in multiples of 16.
Implication	USB 3.0 host controller DCI may hang.
Workaround	DbC software must ensure DCI Control Packets are sent in multiples of 16. And no concurrent OUT EP traffic is occurring while the Control Packets are in progress to the DCI device.
Status	No plan to fix.

26	eSPI Fatal Error Handling
Problem	The eSPI controller may not correctly handle fatal errors occurring on the eSPI bus.
Implication	System implication depends on the type of the fatal error and may result in a system hang. NOTE: A fatal error is a rare event on the eSPI interface and this issue has only been observed by Intel in a synthetic test environment.
Workaround	None.
Status	No plan to fix.

27	PCH PCIe* TX Pin State During L1.0 and L1.1 Substates
Problem	Upon entry to L1.0 or L1.1 Substates the PCH PCIe* TX pins may internally get pulled down to ground instead of maintaining the link common mode voltage.
Implication	PCIe* devices that are in L1.0 or L1.1 may interpret the grounding of the TX pins as an exit event from electrical idle which may cause them to assert their CLKREQ# and exit the L1 Power Management Notes: <ul style="list-style-type: none"> • The issue has only been observed with a single 3rd Party PCIe* Device • The issue is depended on the end point device input squelch sensitivity and if the device sends a Latency Tolerance and Reporting (LTR) Snoop/Non-Snoop Latency Message above 50 Microseconds while entering L1.0 or L1.1 with CLKREQ# de-asserted.
Workaround	None.
Status	No plan to fix.

Errata Details

28	Subsequent Deep S5 and S5 Exits Impacted After "Straight to S5 (Host Stays There)" Resets
Problem	<p>Following a S0 resume from a "Straight to S5 (Host Stays There)" reset, the PCH may enforce earlier wake event restrictions from the "Straight to S5 (Host Stays There)" reset on subsequent Deep S5 and S5 exits causing some wake events not to be recognized by the PCH.</p> <p>NOTE: This issue only occurs on platforms where Deep S5 is enabled. This issue does not impact S3/S4 exits.</p>
Implication	<ul style="list-style-type: none"> • On subsequent Deep S5 exits, the following events would not be able to wake the system: <ul style="list-style-type: none"> — RTC Alarm, PCIe WAKE# pin, and Wake Alarm Device. • On subsequent S5 exits if the S5 entry is due leaving Deep Sx because of ACPRESENT assertion, the following events would not be able to wake the system: <ul style="list-style-type: none"> — RTC Alarm, PCIe WAKE# pin, Wake Alarm Device, GPIOs and Secondary PME# • If system is in S5 for any other reason, this issue would not be present.
Workaround	<p>None</p> <p>NOTE: The Deep S5 / S5 exit restrictions are cleared after DSW_PWROK assertion (G3 power state) or after another global reset occurs (as long as global reset is not of the type "Straight to S5 (Host Stays There)").</p>
Status	No plan to fix.

29	eSPI Bus Mastering
Problem	<p>The eSPI controller may not successfully complete bus mastering cycles from a slave device as described below:</p> <ol style="list-style-type: none"> 1. Upstream memory write from EC may have the last DW dropped if there's an upstream completion of a configuration cycle occurring at the same time 2. The controller may prevent the system from entering a warm reset if an upstream non-posted cycle is pending 3. The controller may not perform ordering between posted/non-posted/completion requests <p>The issue has only been observed in synthetic testing environment</p>
Implication	System may hang.
Workaround	It may be possible for BIOS code changes to workaround this erratum.
Status	No plan to fix.

30	Voltage Floating on USB - Device Mode Capable Port
Problem	During warm reset or host deep reset, the USB port 1 defaults to Device Controller mode and may take ~250 ms to switch back to Host Controller mode. During this time, the USB2 integrated pull downs are disabled and the D+/D- lines may float.
Implication	Device susceptible to SE1 responds unexpectedly and may fail to enumerate.
Workaround	System BIOS should toggle vBus before executing the xHCI init flow after a SUS power loss or a system warm reset.
Status	No plan to fix.

31	USB 3.0 – Jitter Tolerance Margin
Problem	Following an Sx exit, or Cold Reset, BIOS and Intel® ME Firmware may not restore the electrical parameters associated with Rx jitter tolerance margin for the USB 3.0 interface. The issue does not occur on an initial boot from G3 or warm reboot.
Implication	Degradation of jitter tolerance margin on USB 3.0 port may be observed.
Workaround	None.
Status	No plan to fix.

32	Failure of USB Compliance Test TD 7.01 Link Bring-up Test (Subtests 1 and 2)
Problem	Upon receiving Polling.LFPS burst, the xHCI controller send 3 consecutive Polling.LFPSbursts instead of 4 as per xHCI spec - section 7.5.4.3.2.
Implication	USB-IF TD 7.01 Link Bring-up Test (Subtests 1 and 2) may report a failure. Intel has obtained a waiver for TD 7.01. NOTE: Intel has not observed any functional failure.
Workaround	None.
Status	No plan to fix.

33	Intermittent Failure of USB Compliance Test TD3.08
Problem	USB 2.0 port on the xHCI controller may remain in RESUME state for up to additional 20ms after software writes PORTSC.PLS to U0.
Implication	USB-IF xHCI CV TD 3.08 may report a failure. Intel has obtained a waiver for TD 3.08. NOTE: Intel has not observed any functional failure with any commercially available software.
Workaround	None.
Status	No plan to fix.

Errata Details

34	Intel® RST for PCIe Storage - SATA PCI Configuration Read
Problem	If a PCIe link configured for Intel® RST for PCIe Storage is not trained to L0 due to an error condition (such as device misbehavior, board instability, or system mis-configuration, etc.), a read to any SATA PCI Configuration Space register may not be completed. NOTE: This issue has only been observed in a synthetic test environment
Implication	The incomplete transaction may cause a CATERR, resulting in a system hang.
Workaround	None.
Status	No plan to fix.

35	xHCI Controller May Hang on D3 Entry Following a Hot-plug Event
Problem	The xHCI controller may hang on D3 entry if the xHCI driver is unable to service a port status change in between disconnect and re-connect of Super Speed device.
Implication	Due to this erratum, system may hang.
Workaround	A BIOS ASL code change is available in PCH Platform Initiation Code Revision 2.0 or later.
Status	No plan to fix.

36	USB 2.0 PLL May Fail to Lock During S3 Resume
Problem	When a system is woken from S3 using a USB 2.0 device, the USB 2.0 PLL may fail to lock during the initialization process. Then, the eXtensible Host Controller may not send the Start of Frame (SOF) packets at the correct interval as specified per USB 2.0 specification.
Implication	USB 2.0 devices may not enumerate correctly or yellow bang after resuming from S3.
Workaround	A BIOS workaround has been identified and it is included in Kaby Lake platform Silicon Initialization Code rev 2.2.1 or later.
Status	No plan to fix.

37	PCIEXP_WAKE_STS Bit Not Set as Expected
Problem	PCIEXP_WAKE_STS bit (PMC Controller D31:F2, Bit 14) is not set as expected after a PCI Express WAKE# event.
Implication	System Software may not be able to identify wake from PCI Express wake event using PCIEXP_WAKE_STS bit.
Workaround	None.
Status	No plan to fix.

38	xHCI USB Hardware LPM Capability (HLC) Register Reset to the Default Value During D3-D0 Transition
Problem	xHCI USB Hardware LPM Capability (HLC) register 19 offset 8008 defaults back to its default value of "1" after D3-D0 transition.
Implication	System software may read this value and may enable LPM capability on a platform which is configured to disable LPM. NOTE: Intel has only observed this in the Intel Windows* 7 xHCI driver (4.0.5.55 and older) which may check this bit during a driver upgrade.
Workaround	System software (driver) should not rely on the HLC bit. Fixed in Intel xHCI driver 4.0.6.60.
Status	No plan to fix.

39	Intel® Serial I/O Controller DMA LLP 4 GB Boundary Alignment
Problem	If software assigns a 4 GB-aligned address to the Linked List Pointer (LLP_LOn = 0h) for Intel® Serial I/O Controller DMA engine, then the DMA engine interprets this as an empty link list and would not perform DMA transfers.
Implication	An Intel® Serial IO controller (i.e. I2C, GSPI, or UART) may stop operating which may cause the system to hang.
Workaround	Driver software should not assign LLP to a 4 GB-aligned address. NOTE: This issue has been addressed in the Intel Serial IO drivers in the following versions or later: For Microsoft* Windows* 10, I2C device driver rev 30.100.1724.2, SPI device driver rev 30.100.1725.1, and UART device driver rev 30.100.1725.1.
Status	No plan to fix.

40	eMMC / SDXC / SDIO CRC Detection
Problem	The eMMC or SDXC controllers may fail to detect a CRC error if a bit error occurs on the DATA3 signal during read operations when in eMMC HS400 or SDXC DDR50 mode. CRC detection on other DATA signals is not impacted.
Implication	The controller would not flag the CRC error to the driver or application, which could result in data integrity issues. Bit errors on eMMC or SDXC DATA signals are not expected on platforms that follow Intel recommended design guidelines and tuning processes.
Workaround	None Identified. To mitigate the issue, eMMC HS200 or SDXC SDR50 modes can be used instead of HS400 or DDR50.
Status	No plan to fix.

Errata Details

41	USB DbC Or Device Mode Port When Resuming from S3, S4, S5 Or G3 State
Problem	<p>If a PCH USB Type-C* port is configured in Device Mode (or in DbC mode) and connected to an external USB 3.1 host controller, it may cause the USB port to go into a non-functional state in the following scenarios:</p> <ol style="list-style-type: none"> 1. The PCH resumes from S3, S4, S5 state, the port may remain in U2. 2. The port is connected to a USB 3.1 Gen 1 host controller when resuming from S3, S4, S5 or G3, the port may enter into Compliance Mode or an inactive state if Compliance mode is disabled. 3. The port is connected to a USB 3.1 Gen 2 host controller when resuming from S3, S4, S5 or G3, the port may enter an inactive state.
Implication	PCH USB Type-C* port configured in Device Mode (or in DbC mode) may fail to enumerate or become unavailable.
Workaround	None.
Status	No plan to fix.

42	PCIe Root Port CLKREQ# Asserted Low to Clock Active Timing
Problem	During L1 exit, the PCH PCIe Root Ports may exceed the CLKREQ# asserted low to clock active maximum specification due to PCH PCIe clock un-gate path delays.
Implication	<p>PCIe end point device L1 exit instabilities may be observed.</p> <p>NOTE: PCIe end point devices that message LTR latency greater than or equal to 1 μgs are not affected by this.</p>
Workaround	<p>None Identified.</p> <ul style="list-style-type: none"> • Platforms not supporting S0ix with PCIe end point devices that do not support LTR may disable the associated PCH SRCCLKREQ# signal to keep the PCIe clock active during L1. • Platforms supporting S0ix with PCIe end point devices that have LTR latencies less than 1 μgs may disable the associated PCH SRCCLKREQ# signal to keep the PCIe clock active during L1
Status	No plan to fix.

43	xHCI USB 2.0 ISOCH Device Missed Service Interval
Problem	When the xHCI controller is stressed with concurrent traffic across multiple USB ports, the xHCI controller may fail to service USB 2.0 Isochronous IN endpoints within the required service interval.
Implication	<p>USB 2.0 isochronous devices connected to the xHCI controller may experience dropped packets.</p> <p>NOTE: This issue has only been observed in a synthetic environment.</p>
Workaround	None.
Status	No plan to fix.

44	xHCI Short Packet Event Using Non-Event Data TRB
Problem	The xHCI may generate an unexpected short packet event for the last transfer's Transfer Request Block (TRB) when using Non-Event Data TRB with multiples TRBs.
Implication	Transfer may fail due to the packet size error. NOTE: This issue has only been observed in a synthetic environment. No known implication has been identified with commercial software.
Workaround	None identified. Intel recommends software to use Data Event TRBs for short packet completion.
Status	No plan to fix.

45	eSPI SBLCL Register Bit Not Cleared by PLTRST#
Problem	The IOSF-SB eSPI Link Configuration Lock (SBLCL) bit (offset 4000h, bit 27 in eSPI PCR space) is reset by RSMRST# assertion instead of PLTRST# assertion.
Implication	If the SBLCL bit is set to 1, software will not be able to access the eSPI device Capabilities and Configuration register in the reserved address range (0h - 7FFh) until RSMRST# asserts.
Workaround	If software needs to access the eSPI device reserved range 0h - 7FFh while SBLCL bit is set to 1, a RSMRST# assertion should be performed.
Status	No plan to fix.

46	I²S Audio Channels Swapped With High Frame Polarity in Device Mode
Problem	When the I ² S interface is in device mode, the audio controller may not be correctly configured if the audio codec requires high frame polarity.
Implication	Due to this erratum, the left and right audio channels may swap when frame polarity is set to high.
Workaround	None identified.
Status	No plan to fix.



Specification Changes

Specification Changes

There are no Specification Changes in this revision of the specification update.

§ §

Specification Clarifications

1. SX_EXIT_HOLDOFF# Not Functional with eSPI Enabled

Add the following note to the 7th Generation Intel® Processor I/O for U/Y Platforms Datasheet – Volume 1 of 2 (#334658) in the SX_EXIT_HOLDOFF# Signal Description in section 26.4:

NOTE: When eSPI is enabled, SX_EXIT_HOLDOFF# functionality is not available, and assertion of the signal will not impact Sx exit flows.

§ §

Document-Only Change

Document-Only Change

There are no Documentation Changes in this revision of the Specification Update.

§ §