



# **Intel® 700 Series Chipset Family Platform Controller Hub (PCH)**

**Specification Update**

---

***Revision 005***

***July 2023***



You may not use or facilitate the use of this document in connection with any infringement or other legal analysis. You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

All product plans and roadmaps are subject to change without notice.

The products described may contain design defects or errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration. No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at [intel.com](https://www.intel.com).

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries.

\*Other names and brands may be claimed as the property of others.

Copyright© 2022-2023, Intel Corporation. All rights reserved.

# Contents

---

1	Preface.....	6
	1.1 Affected Documents.....	6
	1.2 Nomenclature .....	6
2	Identification Information.....	7
	2.1 Marking .....	7
3	Summary Tables of Changes .....	8
	3.1 Codes Used in Summary Table .....	8
	3.2 Errata Summary Table .....	8
	3.3 Specification Changes .....	9
	3.4 Specification Clarifications .....	9
4	Errata Details .....	10
5	Specification Changes.....	15
6	Specification Clarification .....	16



## Revision History

---

Document Number	Revision Number	Description	Revision Date
743621	001	Initial release	September 2022
	002	Added Errata: <a href="#">014</a>	January 2023
	003	Added Errata: <a href="#">015</a> Added Workstation Intel® Chipset W790, Desktop Intel® Chipset H770 and B760, Mobile Intel® Chipset WM790 and HM770 identification.	May 2023
	004	Added Errata: <a href="#">016</a>	June 2023
	005	Added Errata: <a href="#">017</a>	July 2023

§§

# 1 Preface

---

This document is an update to the specifications contained in the documents listed in the following [Affected Documents](#) table. This document is a compilation of device and document errata and specification clarifications and changes. It is intended for hardware system manufacturers and for software developers of applications, operating system, and tools.

Information types defined in the Nomenclature section of this document are consolidated into the specification update and are no longer published in other documents. This document may also contain information that has not been previously published.

## 1.1 Affected Documents

Document Title	Document Number
Intel® 700 Series Chipset Family Platform Controller Hub (PCH) Datasheet, Volume 1 of 2	<a href="#">743835</a>
Intel® 700 Series Chipset Family Platform Controller Hub (PCH) Datasheet, Volume 2 of 2	<a href="#">743845</a>

## 1.2 Nomenclature

**Errata** are design defects or errors. Errata may cause the behavior of the PCH to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present in all devices.

**Specification Changes** are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

**Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.



## 2 Identification Information

---

### 2.1 Marking

Table 2-1. PCH Lines Component Identification

PCH Stepping	Top Marking (S-Spec)	Notes
B1	SRL02	Workstation Intel® Chipset W790
B1	SRM8V	Desktop Intel® Chipset B760
B1	SRM8T	Desktop Intel® Chipset H770
B1	SRM8P	Desktop Intel® Chipset Z790
B1	SRM8N	Mobile Intel® Chipset WM790
B1	SRM8M	Mobile Intel® Chipset HM770

§§

## 3 Summary Tables of Changes

The following tables indicates the Specification Changes, Errata, Specification Clarifications or Documentation Changes, which apply to the product. Intel may fix some of the errata in a future stepping of the component and account for the other outstanding issues through documentation or specification changes as noted. These tables use the following notations:

### 3.1 Codes Used in Summary Table

Status	Description
Doc	Document change or update that is implemented.
Planned Fix	This erratum may be fixed in a future stepping of the product.
Fixed	This erratum has been previously fixed in Intel® hardware, firmware, or software.
No Fix	There are no plans to fix this erratum.
N/A	This erratum is not applicable to the listed product/stepping or the Specification Change does not apply to the listed product/stepping.
X	Specification Changes applies to the listed product/stepping.

### 3.2 Errata Summary Table

Erratum ID	Stepping	Errata
	B1	
001	No Fix	<a href="#">SATA Enclosure Management LED Messaging</a>
002	No Fix	<a href="#">eSPI SBLCL Register Bit Not Cleared by PLTRST#</a>
003	No Fix	<a href="#">PCIe Clock and PCIe Reference Clock to Processor Maximum Rising/Falling Edge Rate and VCROSS</a>
004	No Fix	<a href="#">USB Audio Offload Traffic with Full-Speed Device Behind Hub</a>
005	No Fix	<a href="#">Integrated GbE Controller Reset on D3 Exit</a>
006	No Fix	<a href="#">xHCI Link Protocol Field Value - USB 3.2 Gen 1x2 and 2x2</a>
007	No Fix	<a href="#">xHCI Force Header Command Incorrect Return Code</a>
008	No Fix	<a href="#">USB VTIO Device Capabilities Field Length</a>
009	No Fix	<a href="#">SLP A# Minimum Assertion Width Timer During G3 Exit</a>
010	No Fix	<a href="#">xHCI Dropped ACK Packet after Upstream Truncated Packet with DPPABORT OS</a>

**Summary Tables of Changes**

Erratum ID	Stepping	Errata
	B1	
011	No Fix	<a href="#">Processor C-States with USB Full-speed or Low-speed Device Hotplug</a>
012	No Fix	<a href="#">Timed GPIO Event May Have a Mismatched Time Stamp</a>
013	No Fix	<a href="#">USB 3.2 Gen 1x1 Port Does Not Send 16 Polling LFPS Burst</a>
014	No Fix	<a href="#">USB 2.0 Full-speed Device Enumeration With Certain Cables</a>
015	No Fix	<a href="#">Precision Time Measurement (PTM) Interpretation Capability Bit Incorrect Register Offset</a>
016	No Fix	<a href="#">ESPI_CS1#, ESPI_CS2#, and ESPI_CS3# Floating Following Initial eSPI Reset Deassertion</a>
017	Fixed	<a href="#">USB Low-Speed or Full-Speed Device Enumeration Failures During Hot-Plug</a>

### 3.3 Specification Changes

No.	Specification Changes
	No specification changes for this revision of the specification update.

### 3.4 Specification Clarifications

No.	Specification Clarifications
	No specification clarification for this revision of this specification update.

§§



## 4 Errata Details

<b>001</b>	<b>SATA Enclosure Management LED Messaging</b>
<b>Problem</b>	When sending a SATA enclosure LED message and all SATA ports are either idle or disabled, the PCH may not transmit the LED message due to an internal clock gating issue.
<b>Implication</b>	The LED status for SATA enclosure may be incorrect.
<b>Workaround</b>	None identified. Enclosure Management SW can poll the Enclosure Management (EM_CTL) - Offset 20h bit 8 register for a 0 value immediately before writing LED messages.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>002</b>	<b>eSPI SBLCL Register Bit Not Cleared by PLTRST#</b>
<b>Problem</b>	The IOSF-SB eSPI Link Configuration Lock (SBLCL) bit (offset 4000h, bit 27 in eSPI PCR space) is reset by RSMRST# assertion instead of PLTRST# assertion.
<b>Implication</b>	If the SBLCL bit is set to 1, software will not be able to access the eSPI device Capabilities and Configuration register in the reserved address range (0h - 7FFh) until RSMRST# asserts.
<b>Workaround</b>	If software needs to access the eSPI device reserved range 0h - 7FFh while SBLCL bit is set to 1, a RSMRST# assertion should be performed.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>003</b>	<b>PCIe Clock and PCIe Reference Clock to Processor Maximum Rising/Falling Edge Rate and VCROSS</b>
<b>Problem</b>	The PCIe Clock Output signals (CLKOUT_PCIE_P/N) and PCIe reference clock signals to processor (CLKOUT_CPUPCIBCLK_P/N) may not meet the maximum Rising/Falling Edge Rate and VCROSS specifications as defined in the PCI Express Card Electromechanical Specification Revision 3.0, section 2.1.3, REFCLK AC Specifications.
<b>Implication</b>	There are no known functional failures due to this erratum.
<b>Workaround</b>	None identified.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>004</b>	<b>USB Audio Offload Traffic with Full-Speed Device Behind Hub</b>
<b>Problem</b>	If USB audio offload is enabled for a USB Full-Speed Isochronous audio device connected behind a USB 2.0 or later hub and there is an active concurrent bulk transfer to another device on any port of the xHCI controller or behind the hub, the controller may stall the offloaded audio traffic and a split transaction error may occur.
<b>Implication</b>	The USB audio offload playback may stop. Audio may be recovered if the audio stream is paused and restarted, the audio device is removed and reconnected, or the audio application is restarted.

## Errata Details

<b>Workaround</b>	None identified. A mitigation for this erratum is available with Intel® Smart Sound Technology version 10.29.00.5574 or later for systems with Microsoft Windows* 11 OS Release or Intel Smart Sound Technology version 10.29.00.7767 or later for systems with Microsoft Windows 10 OS Release. This mitigation will disable audio offload functionality for USB audio devices connected behind a hub.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>005</b>	<b>Integrated GbE Controller Reset on D3 Exit</b>
<b>Problem</b>	Upon GbE controller D3 exit, the GbE host driver performs a controller reset. During this reset, software accesses to the GbE MMIO registers may not complete.
<b>Implication</b>	The system may hang. Note: This erratum has only been observed in a synthetic environment.
<b>Workaround</b>	None identified.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>006</b>	<b>xHCI Link Protocol Field Value - USB 3.2 Gen 1x2 and 2x2</b>
<b>Problem</b>	The xHCI Host Controller reports the value of 0h for the Link Protocol (LP) bits [15:14] in register XECP_SUPP_USB3_6 (MMIO offset 8038h) and XECP_SUPP_USB3_7 (MMIO offset 803Ch), which does not meet the xHCI specification revision 1.2.
<b>Implication</b>	There are no known functional failures due to this erratum.
<b>Workaround</b>	None identified.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>007</b>	<b>xHCI Force Header Command Incorrect Return Code</b>
<b>Problem</b>	The xHCI controller does not return the correct completion code for the Force Header Command as defined in the Section 4.6.16 of the eXtensible Host Controller Interface for Universal Serial Bus (xHCI) Requirements Specification Rev 1.2.
<b>Implication</b>	xHCI CV TD4.12 - Force Header Command Test may report an error. Intel has obtained a waiver for TD 4.12. The Force Header Command is only used by the USB-IF Command Verifier (xHCI CV) tool for device testing. There are no known functional failures due to this erratum.
<b>Workaround</b>	None identified.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>008</b>	<b>USB VTIO Device Capabilities Field Length</b>
<b>Problem</b>	The xHCI spec version 1.2 defines the PCI Express Capability structure offset 04h Device Capabilities (DVSEC) field to be 8 bytes. The USB Virtualization Based Trusted IO (VTIO) Management controller implements the DVSEC field as 12 bytes.
<b>Implication</b>	An USB controller driver may not be able to enable the USB VTIO controller.
<b>Workaround</b>	None identified. To mitigate this erratum, an Independent Software Vendor could account for the field length in the USB controller driver.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>009</b>	<b>SLP_A# Minimum Assertion Width Timer During G3 Exit</b>
<b>Problem</b>	Setting the Disable SLP_X Stretching After SUS Well Power Up (DIS_SLP_X_STRCH_SUS_UP) bit (offset 1020h, bit 12 in PMC_MMIO space) to 1 does not disable the SLP_A# Minimum Assertion Width (SLP_A_MIN_ASST_WDTH) timer (offset 1020h, bit 17 and 16 in PMC_MMIO space).
<b>Implication</b>	G3 exit duration may be extended by the value programmed in the SLP_A_MIN_ASST_WDTH register.
<b>Workaround</b>	None identified.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>010</b>	<b>xHCI Dropped ACK Packet after Upstream Truncated Packet with DPPABORT OS</b>
<b>Problem</b>	If a USB 3.2 Gen 1x1 hub sends an upstream truncated packet with DPPABORT OS (Data Packet Payload Abort Order Set) framing followed by an ACK packet for a previous OUT transfer from the xHCI controller, the ACK packet may be dropped by the xHCI controller.
<b>Implication</b>	A timeout may be observed for the OUT transfer packet. Per the xHCI spec, a xHCI controller driver will issue a warm port reset to the device causing a device re-enumeration.
<b>Workaround</b>	None identified.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>011</b>	<b>Processor C-States with USB Full-speed or Low-speed Device Hotplug</b>
<b>Problem</b>	When doing a hotplug on a USB hub with two or more USB Full-speed or Low-speed devices each with a 1 ms service interval interrupt endpoint, a race condition may occur between the PMC and the xHCI controller.
<b>Implication</b>	The processor may fail to enter C3 or deeper package C-States. Note: This erratum has only been observed in a synthetic environment.
<b>Workaround</b>	None identified. This condition is recovered after the xHCI controller has successfully entered D3.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

## Errata Details

<b>012</b>	<b>Timed GPIO Event May Have a Mismatched Time Stamp</b>
<b>Problem</b>	When a Timed GPIO event is counted in the Event Counter Capture (TGPIOECCV) register (offset 1238h, bits 31 to 0 in PWRMBASE space), the Time Capture (TGPIOTCV) register (offset 1230h, bits 31 to 0 in PWRMBASE space) value is not immediately updated after that event is counted.
<b>Implication</b>	A Timed GPIO event may have a mismatched time stamp.
<b>Workaround</b>	None identified. A Timed GPIO driver can partially mitigate for this erratum by detecting that a TGPIOECCV register change has occurred without a TGPIOTCV register change and then repeatedly re-read the TGPIOTCV register until a change does occur.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>013</b>	<b>USB 3.2 Gen 1x1 Port Does Not Send 16 Polling LFPS Burst</b>
<b>Problem</b>	On USB 3.2 Gen 1x1 only capable ports, including ports configured as USB 3.2 Gen 1x1 by soft strap, the xHCI controller may send only 15 LFPS signals instead of a burst of 16 LFPS signals as specified by the USB 3.2 specification.
<b>Implication</b>	There are no known functional implications due to this erratum. LFPS handshake requires the receiver link partner to only detect 2 LFPS signals. This issue may impact the SuperSpeed compliance test case which checks for the 16 LFPS burst requirements: TD6.4, TD6.5, and TD7.31.
<b>Workaround</b>	None identified.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>014</b>	<b>USB 2.0 Full-speed Device Enumeration With Certain Cables</b>
<b>Problem</b>	The xHCI controller may not complete the detection of the End of Packet Single Ended 0 (EOP SE0) when a USB Full-speed device is connected through a USB 2.0 cable that has a connector-to-connector propagation delay greater than 15.6 ns.
<b>Implication</b>	Due to this erratum, the USB 2.0 Full-speed device may fail to enumerate.
<b>Workaround</b>	None identified.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>015</b>	<b>Precision Time Measurement (PTM) Interpretation Capability Bit Incorrect Register Offset</b>
<b>Problem</b>	The PTM Propagation Delay Adaptation Interpretation B (PTMPDAIB) Bit is implemented at Configuration Space (CFG) Offset 158h instead of at 50h as documented in the PCI-SIG PTM Byte Ordering Adaptation Engineering Change Notice (ECN).
<b>Implication</b>	Due to this erratum, End Point Device (EPD) software that implements the PTM Byte Ordering Adaptation ECN will not be able to program their PTMPDAIB Bit correctly since it is located at a different register offset.
<b>Workaround</b>	None identified. To mitigate this issue, EPD software that implements the PTM Byte Ordering Adaptation ECN must access PTMPDAIB at CFG Offset 158h.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>016</b>	<b>ESPI_CS1#, ESPI_CS2#, and ESPI_CS3# Floating Following Initial eSPI Reset Deassertion</b>
<b>Problem</b>	During Deep Sx exit or booting from G3 state, ESPI_CS1#, ESPI_CS2#, and ESPI_CS3# are momentarily high impedance and may float low following the initial ESPI_RESET# deassertion.
<b>Implication</b>	Due to this erratum, unexpected system behavior may occur on systems with more than one eSPI device.
<b>Workaround</b>	Implement 10 kohm external pull-up resistors to the VCCPRIM_1P8 voltage rail on ESPI_CS1#, ESPI_CS2#, and ESPI_CS3#.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .

<b>017</b>	<b>USB Low-Speed or Full-Speed Device Enumeration Failures During Hot-Plug</b>
<b>Problem</b>	During the hot-plug of a USB 2.0 hub with Low-Speed or Full-Speed device connected behind the hub, a split transaction error may occur during the enumeration of the USB Low-Speed or Full-Speed device.
<b>Implication</b>	Due to this erratum, the USB Low-Speed or Full-Speed device may fail to enumerate when connected to the USB 2.0 hub. This condition is recovered after the xHCI controller has been reset (for example, software setting the xHCI Host Controller Reset (HCRST) bit or by performing a power button override).
<b>Workaround</b>	A BIOS code change has been identified and may be implemented as a workaround for this erratum.
<b>Status</b>	For the steppings affected, refer to the <a href="#">Summary Table of Changes</a> .



## **5**      ***Specification Changes***

---

There are no specification changes in this revision of the Specification Update.

**§§**

## **6**      ***Specification Clarification***

---

There are no specification clarifications in this revision of the Specification Update.

**§§**