



Firmware Management Protocol Reduced Functionality in Intel[®] Ethernet Controllers

Application Note

NEX Cloud Networking Group (NCNG)

Rev. 1.0

June 2023



No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

This document (and any related software) is Intel copyrighted material, and your use is governed by the express license under which it is provided to you. Unless the license provides otherwise, you may not use, modify, copy, publish, distribute, disclose or transmit this document (and related materials) without Intel's prior written permission. This document (and related materials) is provided as is, with no express or implied warranties, other than those that are expressly stated in the license.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors which may cause deviations from published specifications.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

Other names and brands may be claimed as the property of others.

Copyright © 2023, Intel Corporation. All rights reserved.



Revision History

Revision	Date	Comments
1.0	June 16, 2023	Initial release (Public).



1.0 Firmware Functionality Change

Intel is reducing functionality of Firmware Management Protocol (FMP) in the UEFI driver. This change will eliminate excess code in the UEFI driver that is not used by our customers. This change will affect UEFI drivers found in the adapters containing the following:

- Intel® Ethernet Controller I210
- Intel® Ethernet Controller I350
- Intel® 82599 10 GbE Controller
- Intel® Ethernet Controller X540
- Intel® Ethernet Controller X550
- Intel® Ethernet Controller X710/XXV710/XL710
- Intel® Ethernet Controller X710-TM4/AT2

NOTE

This change will not impact the Intel® Ethernet 800 Series driver.

The following is the Firmware Management Protocol structure from the UEFI specification:

```
struct _EFI_FIRMWARE_MANAGEMENT_PROTOCOL {
    EFI_FIRMWARE_MANAGEMENT_PROTOCOL_GET_IMAGE_INFO    GetImageInfo;
    EFI_FIRMWARE_MANAGEMENT_PROTOCOL_GET_IMAGE        GetImage;
    EFI_FIRMWARE_MANAGEMENT_PROTOCOL_SET_IMAGE        SetImage;
    EFI_FIRMWARE_MANAGEMENT_PROTOCOL_CHECK_IMAGE      CheckImage;
    EFI_FIRMWARE_MANAGEMENT_PROTOCOL_GET_PACKAGE_INFO GetPackageInfo;
    EFI_FIRMWARE_MANAGEMENT_PROTOCOL_SET_PACKAGE_INFO SetPackageInfo;
};
```

Looking at the above structure, we will retain support for `GetImageInfo` and `GetPackageInfo` but will remove the remaining functions. All four remaining functions will return `EFI_UNSUPPORTED` status. (`SetPackageInfo()` does it currently).

To summarize the FMP change:

- The `GetImageInfo` and `GetPackageInfo` functions from FMP remain unchanged.
- The `GetImage`, `SetImage`, `CheckImage`, and `SetPackageInfo` functions from FMP will return `EFI_UNSUPPORTED` status for all adapters.
- The 800 Series product is not affected by this change.

