



# Product Change Notification

**Change Notification #:** 119547-01

**Change Title:** Select Intel® Server Boards, Systems and Spares, PCN 119547-01, Product Discontinuance, Product End of Life  
**Reason for Revision:** Adding additional Components SKUs to EOL

**Date of Publication:** May 18, 2023

## Key Characteristics of the Change:

Product Discontinuance

## Forecasted Key Milestones:

|   |                   |
|---|-------------------|
| Product Discontinuance Program Support Begins*      | May 05, 2023      |
| Last Product Discontinuance Order Date*             | June 30, 2023     |
| Orders are Non-Cancelable and Non-Returnable After* | May 05, 2023      |
| Last Product Discontinuance Shipment Date*          | December 22, 2023 |

## Description of Change to the Customer:

**Reason for Revision:** Adding additional Components SKUs to EOL highlighted in Blue in the Products Affected Table below.

Intel is announcing the discontinuance of the Intel® Server Systems, Chassis, Spares and Accessories listed in the "Products Affected/Intel Ordering Codes" table below.

Intel will make best efforts to support all orders placed between the Non-Cancelable and Non-Returnable (NCNR) and the Last Product Discontinuance Order (LPDO) dates. After the LPDO date existing inventory is still orderable, under NCNR terms, and will be filled on a first come first served basis. Deliveries must be accepted within 15 days from the system build date, or order placement date, whichever is later.

Final purchase orders are non-cancelable and non-returnable, notwithstanding any conflicting terms in our quotes, purchase order acknowledgement or Distributor agreements.

Intel has enabled MiTAC to manufacture and sell the discontinued DSG products. MiTAC is an edge-to-cloud IT solutions provider; has been a longstanding partner of DSG, and is the current DSG ODM, manufacturer, test, and integration partner for these systems. Intel and MiTAC are working together to ensure a smooth transition and to support you throughout this process. For information concerning these products, please contact: DSGserverinfo@mitac.com or contact your Intel Authorized Distributor.

**Engineering and Support Guidance for Discontinued Products:**

1. Intel will provide support and maintenance (subject to the following) for all products listed in this PCN purchased from Intel by LPDO for the full period of product warranty.
2. No new OS, peripheral, or adapter validation is planned during the extended life period (defined as the period beginning with the Product Discontinuance Announcement publication date ("the PDA date") and continuing through the end of product warranty). The THOL, supported processor, and tested memory lists are frozen at PDA.
3. No new features or enhancements should be expected, however ECOs may be required during the extended life period to maintain supply lines (e.g., to qualify new vendor due to a component EOL).
4. Intel will provide reasonable commercial efforts in debugging issues during the warranty period for the product after the PDA date has passed. Fixes cannot be committed, but Intel will endeavor to provide reasonable workarounds for the product.

**Customer Impact of Change and Recommended Action:**

Determine your remaining demand for this product and/or evaluate additional sources (if applicable).

For additional product information please contact: [DSGServerInfo@mitac.com](mailto:DSGServerInfo@mitac.com). Please contact your local Intel Distributor if you require more information or need assistance in selecting a replacement product.

Milestone dates are estimates and subject to change based on business and operational conditions

## Products Affected/Intel Ordering Codes:

| Product Name                           | Product Code   | Affected MM# | Replacement Product Code | Replacement MM# |
|--|----------------|--------------|--------------------------|-----------------|
| Intel® Server Board S2600WFTR          | S2600WFTR      | 986004       | M50CYP2SB1U              | 99A3TR          |
| Intel® Server Board S2600WF0R          | S2600WF0R      | 986005       | M50CYP2SB1U              | 99A3TR          |
| Intel® Server Board S2600WFQR          | S2600WFQR      | 986006       | M50CYP2SB1U              | 99A3TR          |
| Intel® Server System R1304WF0YSR       | R1304WF0YSR    | 986047       | M50CYP1UR204             | 99A3TX          |
| Intel® Server System R1304WF0ZSR       | R1304WF0ZSR    | 99AW7N       | M50CYP1UR204             | 99A3TX          |
| Intel® Server System R1304WFTYSR       | R1304WFTYSR    | 986048       | M50CYP1UR204             | 99A3TX          |
| Intel® Server System R1304WFTZSR       | R1304WFTZSR    | 99AW7M       | M50CYP1UR204             | 99A3TX          |
| Intel® Server System R1208WF0YSR       | R1208WF0YSR    | 986058       | M50CYP1UR212             | 99A3TW          |
| Intel® Server System R1208WF0ZSR       | R1208WF0ZSR    | 99AW7L       | M50CYP1UR212             | 99A3TW          |
| Intel® Server System R1208WFTYSR       | R1208WFTYSR    | 986007       | M50CYP1UR212             | 99A3TW          |
| Intel® Server System R1208WFTZSR       | R1208WFTZSR    | 99AW7C       | M50CYP1UR212             | 99A3TW          |
| Intel® Server System R1208WFQYSR       | R1208WFTZSR    | 986059       | M50CYP1UR212             | 99A3TW          |
| Intel® Server System R1208WFQZSR       | R1208WFQZSR    | 99AW7H       | M50CYP1UR212             | 99A3TW          |
| Intel® Server System R2208WFTZSR       | R2208WFTZSR    | 986049       | M50CYP2UR208             | 99A3TT          |
| Intel® Server System R2208WF0ZSR       | R2208WF0ZSR    | 986050       | M50CYP2UR208             | 99A3TT          |
| Intel® Server System R2208WFQZSR       | R2208WFQZSR    | 986055       | M50CYP2UR208             | 99A3TT          |
| Intel® Server System R2224WFTZSR       | R2224WFTZSR    | 986051       | M50CYP2UR208             | 99A3TT          |
| Intel® Server System R2308WFTZSR       | R2308WFTZSR    | 986052       | M50CYP2UR208             | 99A3TT          |
| Intel® Server System R2312WFTZSR       | R2312WFTZSR    | 986053       | M50CYP2UR312             | 99A3TV          |
| Intel® Server System R2312WF0NPR       | R2312WF0NPR    | 986054       | M50CYP2UR312             | 99A3TV          |
| 1U 1-Slot PCIe* Riser Card             | F1UL16RISER3   | 958249       |                          |                 |
| 2U 3-Slot PCIe* Riser Card             | A2UL8RISER2    | 934885       |                          |                 |
| 2U 2-Slot PCIe* Riser Card             | A2UL16RISER2   | 934886       | CYP2URISER2DBL           | 99A3P7          |
| 2U 2-Slot Short Riser Card             | A2UX8X4RISER   | 934883       |                          |                 |
| 2U Hot-Swap 8 x 2.5" Dual-Port Upgrade | A2U8X25S3DPDK2 | 958247       |                          |                 |
| 2U Hot-Swap 8 x 2.5" SAS/NVMe Combo    | A2U8X25S3PHS   | 955858       |                          |                 |
| Intel® Server Chassis R1304WFXXX       | R1304WFXXX     | 99AWZA       |                          |                 |
| Intel® Server Chassis R1208WFXXX       | R1208WFXXX     | 952621       |                          |                 |
| Intel® Server Chassis R2000WFXXX       | R2000WFXXX     | 975897       |                          |                 |
| Intel® Server Chassis R2312WFXXX       | R2312WFXXX     | 952624       |                          |                 |
| 950 mm long, cable kit                 | AXXCBL950HDHD  | 936122       |                          |                 |
| 875 mm long, cable kit                 | AXXCBL875HDHD  | 936123       |                          |                 |
| 800 mm long, cable kit                 | AXXCBL800HDHD  | 937312       |                          |                 |
| 730 mm long, cable kit                 | AXXCBL730HDHD  | 936178       |                          |                 |
| 650 mm long, cable kit                 | AXXCBL650HDHD  | 937129       |                          |                 |
| 650 mm long, cable kit                 | AXXCBL650HDHRT | 958254       |                          |                 |
| 850 mm long, cable kit                 | AXXCBL850HDHRS | 958255       |                          |                 |
| 850 mm long, cable kit                 | AXXCBL850HDHRT | 958257       |                          |                 |
| 470 mm long, cable kit                 | AXXCBL470CVCR  | 958258       |                          |                 |
| 530 mm long, cable kit                 | AXXCBL530CVCR  | 958260       |                          |                 |
| 730 mm long, cable kit                 | AXXCBL730HDHD  | 936178       |                          |                 |
| 650 mm long, cable kit                 | AXXCBL650HDHD  | 937129       |                          |                 |
| 450 mm long, cable kit                 | AXXCBL450HD7S  | 936428       |                          |                 |
| 650 mm long, cable kit                 | AXXCBL650HDHRT | 958254       |                          |                 |
| 850 mm long, cable kit                 | AXXCBL850HDHRS | 958255       |                          |                 |

| Product Name                               | Product Code    | Affected MM# | Replacement Product Code | Replacement MM# |
|--|-----------------|--------------|--------------------------|-----------------|
| 850 mm long, cable kit                     | AXXCBL850HDHRT  | 958257       |                          |                 |
| 470 mm long, cable kit                     | AXXCBL470CVCR   | 958258       |                          |                 |
| 530 mm long, cable kit                     | AXXCBL530CVCR   | 958260       |                          |                 |
| 600 mm long, cable kit                     | AXXCBL600CVCR   | 959345       |                          |                 |
| 700 mm long, cable kit                     | AXXCBL700CVCR   | 958261       |                          |                 |
| 800 mm long, cable kit                     | AXXCBL800CVCR   | 958262       |                          |                 |
| 620 mm long, cable kit                     | AXXCBL620CRCR   | 958263       |                          |                 |
| 945 mm Retimer cable kit                   | A1U4PRTCXCXK    | 958358       |                          |                 |
| 815 mm Retimer cable kit                   | A2U4PRTCXCXK    | 958264       |                          |                 |
| 470 mm long, cable kit                     | AXXCBL470CVCR   | 958258       |                          |                 |
| 890 mm 1U 4 port switch cable kit          | A1U4PSWCXCVK    | 964522       |                          |                 |
| 755 mm 2U 4 port switch cable kit          | A2U4PSWCXCXK1   | 958266       |                          |                 |
| 875 mm 2U 4 port switch cable kit          | A2U4PSWCXCXK2   | 958267       |                          |                 |
| 725 mm 2U 4 port switch cable kit          | A2U8PSWCXCXK1   | 958268       |                          |                 |
| 875 mm 2U 4 port switch cable kit          | A2U8PSWCXCXK2   | 958270       |                          |                 |
| 810 mm 2U 4 port switch cable kit          | A2U8PSWCXCXK3   | 958272       |                          |                 |
| 700 mm long, cable kit                     | AXXCBL700HDCV   | 958273       |                          |                 |
| 720 mm long (2ea), cable kit               | A1U4PTRICXCVK   | 984361       |                          |                 |
| 2U Rear Mount Hot Swap Drive Bay           | A2UREARHSDK2    | 958243       |                          |                 |
| 2U Fixed Mount SSD and Rear Drive Bay      | A2UCBLSSD       | 937328       |                          |                 |
| 1U Standard Heat Sink                      | FXXCA78X108HS   | 948935       |                          |                 |
| 1U 78mm by 108mm Heat Sink                 | F1UCA78X108HS35 | 958274       |                          |                 |
| 4-Port PCIe* (x16 to x16) SSD Retimer Add- | AXXP3RTX16040   | 958240       |                          |                 |
| 2U Rear Mount Hot Swap Drive Bay           | A2UREARHSDK2    | 958243       |                          |                 |
| 2U Fixed Mount SSD and Rear Drive Bay      | A2UCBLSSD       | 937328       |                          |                 |
| 1U Standard Heat Sink                      | FXXCA78X108HS   | 948935       |                          |                 |
| 1U 78mm by 108mm Heat Sink                 | F1UCA78X108HS35 | 958274       |                          |                 |
| 4-Port PCIe* (x16 to x16) SSD Retimer Add- | AXXP3RTX16040   | 958240       |                          |                 |
| 2U Rear Mount Hot Swap Drive Bay           | A2UREARHSDK2    | 958243       |                          |                 |
| 2U Fixed Mount SSD and Rear Drive Bay      | A2UCBLSSD       | 937328       |                          |                 |
| 1U Standard Heat Sink                      | FXXCA78X108HS   | 948935       |                          |                 |
| 1U 78mm by 108mm Heat Sink                 | F1UCA78X108HS35 | 958274       |                          |                 |
| 4-Port PCIe* (x16 to x16) SSD Retimer Add- | AXXP3RTX16040   | 958240       |                          |                 |
| 4 Port PCIe* x8 Switch Add-in Card         | AXXP3SWX08040   | 958241       |                          |                 |
| 8 Port PCIe* x8 Switch Add-in Card         | AXXP3SWX08080   | 958242       |                          |                 |
| 2U 8x3.5" Front Mount Hot Swap Backplane   | A2U8X35S3HSDK1  | 958246       |                          |                 |
| High Airflow Air Duct Kit                  | AWFCOPRODUCTAD  | 961767       | CYPGPGPUKIT              | 99A3RD          |
| High Airflow Air Duct Bracket Kit          | AWFCOPRODUCTBK  | 961675       |                          |                 |
| Front Panel Board                          | FXXFPANEL2      | 937543       |                          |                 |
| 1U Spare Fan Assembly (3 Fans)             | FR1UFAN10PW     | 974906       |                          |                 |
| 2U Spare Fan (2 Fans/Kit)                  | FR2UFAN60HSW    | 934990       |                          |                 |
| 4x3.5" Spare Hot Swap Backplane            | FR1304S3HSBP    | 934887       |                          |                 |
| 2U Spare Fan (2 Fans/Kit)                  | FR2UFAN60HSW    | 934990       |                          |                 |
| 4x3.5" Spare Hot Swap Backplane            | FR1304S3HSBP    | 934887       |                          |                 |
| 8x2.5" SAS/NVMe* Hot Swap Backplane        | F1U8X25S3PHS    | 955868       |                          |                 |
| 8x3.5" Hot Swap Backplane                  | F2U8X35S3HSBP   | 934892       |                          |                 |
| 8x2.5" SAS/NVMe* Hot Swap Backplane        | F2U8X25S3PHS    | 955870       |                          |                 |

| Product Name  | Product Code                   | Affected MM#           | Replacement Product Code | Replacement MM# |
|---|--------------------------------|------------------------|--------------------------|-----------------|
| 12x3.5" SAS and 2x NVMe* Hot Swap                     | F2U12X35S3PH                   | 955869                 |                          |                 |
| 450 mm long, cable kit                                | AXXCBL450HD7S                  | 936428                 |                          |                 |
| <a href="#">GPGPU cable accessory</a>                 | <a href="#">AXXGPGPUCABLE</a>  | <a href="#">919761</a> |                          |                 |
| <a href="#">RAID Cable Kit with two 650mm High</a>    | <a href="#">AXXCBL650HDMS</a>  | <a href="#">927237</a> |                          |                 |
| <a href="#">Optical Disk Drive (ODD) Data Cable</a>   | <a href="#">AXXCBL880SATA</a>  | <a href="#">922988</a> |                          |                 |
| <a href="#">1U/2U Rack Handle Kit</a>                 | <a href="#">A2UHANDLKIT</a>    | <a href="#">936038</a> |                          |                 |
| <a href="#">2U+ Premium quality rails with no CMA</a> | <a href="#">AXXSHRTRAIL</a>    | <a href="#">939210</a> |                          |                 |
| <a href="#">1U Premium quality rails with no CMA</a>  | <a href="#">A1USHRTRAIL</a>    | <a href="#">939208</a> |                          |                 |
| <a href="#">1U Premium quality rails with CMA</a>     | <a href="#">A1UFULLRAIL</a>    | <a href="#">939207</a> |                          |                 |
| <a href="#">1U/2U 2-Post fixed mount bracket kit</a>  | <a href="#">AXX2POSTBRCKT</a>  | <a href="#">918808</a> |                          |                 |
| <a href="#">1U/2U RMFBU Mounting Option Kit</a>       | <a href="#">AWTAUXBBUBKT</a>   | <a href="#">937082</a> |                          |                 |
| <a href="#">1U Premium quality rails with CMA</a>     | <a href="#">AXX1U2UCMA</a>     | <a href="#">913117</a> |                          |                 |
| <a href="#">1100W AC Common Redundant Power</a>       | <a href="#">AXX1100PCRPS</a>   | <a href="#">936183</a> |                          |                 |
| <a href="#">Serial Port Cable Kit</a>                 | <a href="#">AXXRJ45DB93</a>    | <a href="#">920430</a> |                          |                 |
| <a href="#">Slimline SATA DVDROM Drive</a>            | <a href="#">AXXSATADVDRUM</a>  | <a href="#">937569</a> |                          |                 |
| <a href="#">Slimline SATA DVD+/- ROM Drive</a>        | <a href="#">AXXSATADVDRWRO</a> | <a href="#">937575</a> |                          |                 |

## PCN Revision History:

**Date of Revision:**

May 05, 2023

May 18, 2023

**Revision Number:**

00

01

**Reason:**

Originally Published PCN

Adding additional Components to EOL



# Product Change Notification

## 119547-01

### Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at [www.intc.com](http://www.intc.com).

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)  
**Japan Email:** [jcb.ijkk@intel.com](mailto:jcb.ijkk@intel.com)