



Product Change Notification

Change Notification #: 119013-00
Change Title: Min-SAS HD, I2C, backplane power cable MYP1UCBL, 1U Power distribution Board MYP1UPDB, 1U PCIe x16 Riser Card MYP1URISER, and Intel® Server System M20MYP1UR, PCN 119013-00, Product Discontinuance, End of life
Date of Publication: April 07, 2022

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Product Discontinuance Program Support Begins	April 07, 2022
Orders for Discontinued Products Become Non-Cancelable	June 01, 2022
Last Product Discontinuance Order Date	July 01, 2022
Last Product Discontinuance Shipment Date	August 31, 2022

Description of Change to the Customer:

Intel is announcing the discontinuance of the products listed in the "Products Affected/Intel Ordering Codes" table below.

Intel will make commercially reasonable efforts to support all orders placed between the Non-Cancelable and Non-Returnable (NCNR) and the Last Product Discontinuance Order (LPDO) dates. Intel will discontinue builds on the LPDO date. After the LPDO date existing inventory is still orderable, under NCNR terms, and will be filled as Intel considers appropriate. Deliveries must be accepted within 90 days from the LPDO date.

Final purchase orders are non-cancelable and non-returnable, notwithstanding any conflicting terms in our quotes, purchase order acknowledgement or Distributor agreements.

Intel reserves the right to change the products because of material source restriction.

Engineering and Support Guidance for Discontinued Products:

1. No new OS, peripheral or adaptor validation is planned during the extended life period. The THOL, supported processor and tested memory lists are frozen at PDA.
2. No new features enhancements should be expected, however ECOs may be required during the extended life period to maintain supply lines (e.g., to qualify new vendor due to a component EOL).
3. Intel will provide reasonable commercial efforts in debugging issues during the warranty period for the product after the PDA date has passed. Fixes cannot be committed, but Intel will endeavor to provide reasonable workarounds for the product.

Customer Impact of Change and Recommended Action:

Determine your remaining demand for this product and/or evaluate additional sources (if applicable).

Lead-times on products with announced product discontinuance can typically stretch to 12 weeks and volumes are not buffered during the PDA period. Please work with your Intel representative on your quarterly demand forecast in order to reduce lead-times to 2-4 Weeks.

Please contact your local Intel Sales Office or Distributor if you require more information or need assistance in selecting a replacement product.

Milestone dates are estimates and subject to change based on business and operational conditions.

Products Affected/Intel Ordering Codes:

Marketing Name	Product Code	Affected MM#
Intel® Server System M20MYP1UR, Single	M20MYP1UR	999WRX
1U PCIe x16 Riser Card MYP1URISER, Single	MYP1URISER	99A2D6
1U Power distribution Board MYP1UPDB, Single	MYP1UPDB	99A2D8
Min-SAS HD, I2C, backplane power cable MYP1UCBL, Single	MYP1UCBL	99A2DA

PCN Revision History:

Date of Revision:

April 07, 2022

Revision Number:

00

Reason:

Originally Published PCN



Product Change Notification

119013-00

Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at www.intc.com.

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com