



Product Change Notification

Change Notification #: 119543-02

Change Title: Select Intel® Server Boards, Intel® Compute Modules, Intel® Server Chassis and Spares
PCN 119543-02, Product Discontinuance, Product End of Life
Reason for Revision: Removing the recommended replacement product 999D4J for affected MMID 920970

Date of Publication: June 2, 2023

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Product Discontinuance Program Support Begins	May 05, 2023
Orders are Non-Cancelable and Non-Returnable After	May 05, 2023
Last Product Discontinuance Order Date	June 30, 2023
Last Product Discontinuance Shipment Date	December 22, 2023

Description of Change to the Customer:

Reason for Revision: Removing the recommended replacement product 999D4J for affected MMID 920970 from the Product table below.

Intel is announcing the discontinuance of the Intel® Server Chassis, Spares, and Accessories listed in the "Products Affected/Intel Ordering Codes" table below.

Intel will make best efforts to support all orders placed between the Non-Cancelable and Non-Returnable (NCNR) and the Last Product Discontinuance Order (LPDO) dates. After the LPDO date existing inventory is still orderable, under NCNR terms, and will be filled on a first come first served basis.

Final purchase orders are non-cancelable and non-returnable, notwithstanding any conflicting terms in our quotes, purchase order acknowledgment, or Distributor agreements.

Engineering and Support Guidance for Discontinued Products:

1. Intel will provide support and maintenance (subject to the following) for all products listed in this PCN purchased from Intel by LPDO for the full period of product warranty.
2. No new OS, peripheral, or adapter validation is planned during the Extended Life Period . The THOL, supported processor, and tested memory lists are frozen at PDA.
3. No new features or enhancements should be expected, however ECOs may be required during the Extended Life Period to maintain supply lines (e.g., to qualify new vendor due to a component EOL).
4. Intel will provide reasonable commercial efforts in debugging issues during the warranty period for the product after the PDA date has passed. Fixes cannot be committed, but Intel will endeavor to provide reasonable workarounds for the product.

Customer Impact of Change and Recommended Action:

Milestone dates are estimates and subject to change based on business and operational conditions.

Note: Replacement SKUs have been listed where available. However, all replacements SKUs listed are also being discontinued per other PCNs where the Last Order Date is June 30, 2023.

Please contact your local Intel Distributor if you require more information or need assistance in selecting a replacement product.

Products Affected/Intel Ordering Codes:

Marketing Name	Product Code	Affected MM#	Recommended Replacement Product Code	Recommended Replacement MM#
Intel® RAID Drive Encryption Management (Gen2), Single	AXXRPFKDE2	915317		
Intel® RAID C600 Upgrade Key RKSATA4R5, 5 Pack	RKSATA4R5	916346	VROCPREMMOD	951606
Enhanced Value RAIL AXXELVRAIL, Single	AXXELVRAIL	920970	FCXXRAILKIT	999D4J
40x56mm Spare Dual Rotor Fan FXX4056DRFAN2, Single	FXX4056DRFAN2	935566		
Spare 12Gb SAS/SATA 12 x 3.5" Backplane FHW12X35HS12G, Single	FHW12X35HS12G	935567		
Power Distribution Board Spare FXXCRPSPDB2, Single	FXXCRPSPDB2	935576	FCXXPDBASSMBL	999D4G
Spare Front Control Panel Kit FH2000FPANEL2, Single	FH2000FPANEL2	935578		
2/4U Premium Rail AXXFULLRAIL (with CMA support), Single	AXXFULLRAIL	939209		
Spare Power in Backplane Bridge Board Module FXXCRPSPIB, Single	FXXCRPSPIB	943484	FCXXPDBASSMBL	999D4G
Remote Management Module 4 Lite 2 AXXRMM4LITE2, Single	AXXRMM4LITE2	946514		
2130W AC Common Redundant Power Supply	FXX2130PCRPS	948196	FCXX2100CRPS	999D4L

Marketing Name	Product Code	Affected MM#	Recommended Replacement Product Code	Recommended Replacement MM#
FXX2130PCRPS (Platinum Efficiency), Single				
Intel® Server Chassis H2224XXLR3, Single	H2224XXLR3	948907		
4 Port SATA Bridge Board AHWBPBGB, Single	AHWBPBGB	948925		
4 Port 12G SAS Bridge Board (RAID 0/1/10) AHWBP12GBGB, Single	AHWBP12GBGB	948926		
4 Port 12G SAS Bridge Board (RAID 0/1/10/5) AHWBP12GBGBR5, Single	AHWBP12GBGBR5	948927		
6 Port 12G SAS/NVMe* Combo Bridge Board AHWBPBGB24, Single	AHWBPBGB24	948928		
Intel® RAID Bridge Board AHWBPBGB24R, Single	AHWBPBGB24R	948929		
6 Port 12G Pass Through Bridge Board AHWBPBGB24P, Single	AHWBPBGB24P	948930		
1U PCI Express x16 Riser Card for Low-profile PCIe* Card AHW1URISER1 (Slot 1), Single	AHW1URISER1	948931		
1U PCI Express x16 Riser Card for Low-profile PCIe* Card and M.2 Device AHW1UM2RISER2 (Slot 2), Single	AHW1UM2RISER2	948932	TNP1UCRRISER	99AF4H
Spare 12Gb SAS/SATA 24 x 2.5'' Backplane Kit (with BIB) FHW24X25HSBP, Single	FHW24X25HSBP	948934		
Spare 4-Port Node Power Board FHWBPNPB, Single	FHWBPNPB	952109		
Intel® Server Chassis H2312XXLR3, Single	H2312XXLR3	954487		
2U Hot-swap backplane spare FHW04X35HSBP (for Intel® Server Chassis H2204XXLRE), Single	FHW04X35HSBP	956374		
Spare 1U Standard Front Heat Sink FXXHP78X108HS (Ex-A1 78mmx108mm), Single	FXXHP78X108HS	956548	TNP1UHSF	99A2F9
Intel® Server Chassis H2204XXLRE, Single	H2204XXLRE	957322		
2.5 inch Tool Less Hot-Swap Drive Carrier FXX25HSCAR3, Single	FXX25HSCAR3	958244		

Marketing Name	Product Code	Affected MM#	Recommended Replacement Product Code	Recommended Replacement MM#
3.5 inch Tool Less Hot-Swap Drive Carrier FXX35HSCAR2, Single	FXX35HSCAR2	958245		
Spares Non-fabric CPU clips FXXCPUCLIP, Single	FXXCPUCLIP	958248		
VGA cable accessory AXXBPVIDCBL, Single	AXXBPVIDCBL	958366		
Bolster Plate Ensulator Cover for CPU1 AXXBPBPINSCOV, Single	AXXBPBPINSCOV	958483		
4 Port SATA Bridge Board AHWBP12GBGBIT, Single	AHWBP12GBGBIT	960803		
1U Standard Front Heat-Sink 78x108mm FXX2678X108HS, Single	FXX2678X108HS	964013	TNP1UHSB	99A2FA
Intel® Compute Module HNS2600BPQR, Single	HNS2600BPQR	985900	D50TNP1MHCRAC	99A2DZ
Intel® Server Board S2600BPBR, OEM 10 Pack	BBS2600BPBR	986113	D50TNP1SB	99A2AT
Intel® Server Board S2600BPSR, OEM 10 Pack	BBS2600BPSR	986114		
Intel® Server Board BBS2600BPQR, 10 Pack	BBS2600BPQR	986115	D50TNP1SBCR	99AA23
Intel® Compute Module HNS2600BPBR, Single	HNS2600BPBR	986116	D50TNP1MHCPAC	99A2DZ
Intel® Compute Module HNS2600BPSR, Single	HNS2600BPSR	986117	D50TNP1MHCRAC	99A2DZ
Intel® Compute Module HNS2600BPB24R, Single	HNS2600BPB24R	986118	D50TNP1MHCRAC	99A2DZ
Intel® Compute Module HNS2600BPS24R, Single	HNS2600BPS24R	986119	D50TNP1MHEVAC	99A2DZ
Intel® Compute Module HNS2600BPQ24R, Single	HNS2600BPQ24R	986120	D50TNP1MHCPAC	99A2DZ
Intel® Compute Module Liquid-Cooled HNS2600BPBRCT, Single	HNS2600BPBRCT	99AF58	D50TNP1MHCRLC	99A84F
Liquid-Cooling Loop Kit AXXBPCTKIT, Single	AXXBPCTKIT	99AF5A		

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
May 05, 2023	00	Originally Published PCN
May 18, 2023	01	Add additional components
June 02, 2023	02	Removing the recommended replacement product 999D4J for affected MMID 920970



Product Change Notification

119543-02

Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at www.intc.com.

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com