

## **Product Change Notification**

Change Notification #: 116894 - 02

Change Title: Select Intel® Server Boards, Intel® Server Systems

& Intel® Compute Modules,

PCN 116894-02, Product Discontinuance,

**End of Life** 

Reason for Revision: Adding MM#975885, MM#975884 and MM#975890 to the products

affected table

Date of Publication: February 28, 2020

#### **Key Characteristics of the Change:**

Product Discontinuance

#### **Forecasted Key Milestones:**

Product Discontinuance Program Support Begins:	April 22, 2019
Last Product Discontinuance Order Date:	August 22, 2019
Orders are Non-Cancelable and Non-Returnable After:	May 22, 2019
Last Product Discontinuance Shipment Date:	December 22, 2019

#### **Description of Change to the Customer:**

Reason for Revision: Adding MM#975885, MM#975884 and MM#975890 to the products affected table

Intel is announcing the discontinuance of selected Intel® Server Boards, Intel® Server Systems & Intel® Compute Modules as listed in the "Products Affected/Intel Ordering Codes" table below.

Intel will make best efforts to support all orders placed between the Non-Cancelable and Non-Returnable (NCNR) and the Last Product Discontinuance Order (LPDO) dates. Intel will discontinue builds on the LPDO date. After the LPDO date existing inventory is still orderable, under NCNR terms, and will be filled on a first come first served basis. Deliveries must be accepted within 120 days from the LPDO date.

Final purchase orders are non-cancelable and non-returnable, notwithstanding any conflicting terms in our quotes, purchase order acknowledgement or Distributor agreements.

Intel reserves the right to change the products because of material source restriction.

Page 1 of 4 PCN116894-02

#### **Engineering and Support Guidance for Discontinued Products:**

- 1. No new OS, peripheral or adaptor validation is planned during the extended life period. The THOL, supported processor and tested memory lists are frozen at PDA.
- 2. No new features enhancements should be expected, however ECOs may be required during the extended life period to maintain supply lines (e.g. to qualify new vendor due to a component EOL).
- Intel will provide reasonable commercial efforts in debugging issues during the warranty period for the
  product after the PDA date has passed. Fixes cannot be committed, but Intel will endeavor to provide
  reasonable workarounds for the product.

#### **Customer Impact of Change and Recommended Action:**

Determine your remaining demand for this product and/or evaluate additional sources (if applicable).

Lead-times on products with announced product discontinuance can typically stretch to 12 weeks and volumes are not buffered during the PDA period. Please work with your Intel representative on your quarterly demand forecast in order to reduce lead-times to 2-4 Weeks.

Please contact your local Intel Sales Office or Distributor if you require more information or need assistance in selecting a replacement product.

Milestone dates are estimates and subject to change based on business and operational conditions.

**Products Affected / Intel Ordering Codes:** 

Products Affected / Intel Ordering Codes.						
Product Name	Product Code	Affected MM#	Recommended Replacement	Recommended Replacement		
			Product Code	MM#		
Intel® Server Board S2600WFT	S2600WFT	952641	S2600WFTR	986004		
Intel® Server Board S2600WF0	S2600WF0	952644	S2600WF0R	986005		
Intel® Server Board S2600WFQ	S2600WFQ	952645	S2600WFQR	986006		
Intel® Server System R1304WF0YS	R1304WF0YS	952626	R1304WF0YSR	986047		
Intel® Server System R1304WF0YS	R1304WF0YS	975885	R1304WF0YSR	986047		
Intel® Server System R1304WFTYS	R1304WFTYS	952625	R1304WFTYSR	986048		
Intel® Server System R1304WFTYS	R1304WFTYS	975884	R1304WFTYSR	986048		
Intel® Server System R1208WFTYS	R1208WFTYS	975886	R1208WFTYSR	986007		
Intel® Server System R2208WFTZS	R2208WFTZS	975889	R2208WFTZSR	986049		
Intel® Server System R2208WF0ZS	R2208WF0ZS	975888	R2208WF0ZSR	986050		
Intel® Server System R2208WFQZS	R2208WFQZS	952637	R2208WFQZSR	986055		
Intel® Server System R2208WFQZS	R2208WFQZS	975890	R2208WFQZSR	986055		
Intel® Server System R2224WFTZS	R2224WFTZS	975895	R2224WFTZSR	986051		
Intel® Server System R2308WFTZS	R2308WFTZS	975887	R2308WFTZSR	986052		
Intel® Server System R2312WFTZS	R2312WFTZS	975892	R2312WFTZSR	986053		
Intel® Server System R2312WF0NP	R2312WF0NP	975812	R2312WF0NPR	986054		
Intel® Server System R2312WFQZS	R2312WFQZS	955877	NA	NA		
Intel® Server System R2224WFQZS	R2224WFQZS	955875	NA	NA		
Intel® Server Board S2600BPB	BBS2600BPB	948899	BBS2600BPBR	986113		
Intel® Server Board S2600BPQ	BBS2600BPQ	948900	BBS2600BPQR	986115		
Intel® Server Board S2600BPS	BBS2600BPS	952609	BBS2600BPSR	986114		
Intel® Compute Module HNS2600BPB	HNS2600BPB	976668	HNS2600BPBR	986116		
Intel® Compute Module HNS2600BPS	HNS2600BPS	976670	HNS2600BPSR	986117		
Intel® Compute Module HNS2600BPBLC	HNS2600BPBLC	961401	HNS2600BPBLCR	986121		
Intel® Compute Module HNS2600BPB24	HNS2600BPB24	976671	HNS2600BPB24R	986118		
Intel® Compute Module HNS2600BPQ24	HNS2600BPQ24	976675	HNS2600BPQ24R	986120		
Intel® Compute Module HNS2600BPQ	HNS2600BPQ	948901	HNS2600BPQR	985900		

Page 2 of 4 PCN116894-02

Product Name	Product Code	Affected MM#	Recommended	Recommended
			Replacement	Replacement
			Product Code	MM#
Intel® Compute Module HNS2600BPS24	HNS2600BPS24	976676	HNS2600BPS24R	986119
Intel® Compute Module HNS2600BPBLC24	HNS2600BPBLC24	977207	HNS2600BPBLC24R	986122
Intel® Server Board S2600STB	S2600STB	957180	S2600STBR	986246
Intel® Server Board S2600STQ	S2600STQ	957318	S2600STQR	986307
Intel® Server Board S2600STB (10 Pack)	BBS2600STB	959820	BBS2600STBR	986308
Intel® Server Board S2600STQ (10 Pack)	BBS2600STQ	959727	S2600STQR	986307

### **PCN Revision History:**

Date of Revision:	<b>Revision Number:</b>	Reason:
April 22, 2019	00	Originally Published PCN
May 15, 2019	01	Adding HNS2600BPQ
February 28, 2020	02	Adding MM#975885, MM#975884
		and MM#975890

Page 3 of 4 PCN116894-02



# Product Change Notification 116894 - 02

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com
Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: <a href="mailto:eccb@intel.com">eccb@intel.com</a>
Japan Email: <a href="mailto:jccb.ijkk@intel.com">jccb.ijkk@intel.com</a>

Copyright © Intel Corporation 2020. Other names and brands may be claimed as the property of others.

3D XPoint, Axxia, Basis, Basis Peak, BlueMoon, BunnyPeople, Celeron, Centrino, Cilk, Curie, Flexpipe, Intel, the Intel logo, Intel Atom, Intel CoFluent, Intel Core, Intel. Experience What's Inside, the Intel. Experience What's Inside logo, Intel Inside, the Intel Inside logo, Intel Inside, Intel Inside logo, Intel Inside logo, Intel Inside logo, Intel Inside logo, Intel Wero, Intel Xeon Phi, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Iris, Itanium, MCS, MMX, Optane, Ostro, Pali, Pentium, picoArray, Picochip, picoXcell, Puma, Quark, SMARTi, Soletta, Sound Mark, StarPro, Stay With It, the Engineering Stay With It logo, StreamSight, Tarari, The Journey Inside, Thunderbolt, the Thunderbolt logo, Transcede, True Key, Ultrabook, VTune, Xeon, X-GOLD, XMM, X-PMU and XPOSYS are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries.

Microsoft, Windows, and the Windows logo are trademarks, or registered trademarks of Microsoft Corporation in the United States and/or other countries. Java is a registered trademark of Oracle and/or its affiliates. Bluetooth is a trademark owned by its proprietor and used by Intel Corporation under license. Intel Corporation uses the Palm OS\* Ready mark under license from Palm, Inc. OpenCL and the OpenCL logo are trademarks of Apple Inc. used by permission by Khronos. Learn how to use Intel Trademarks and Brands correctly at <a href="http://www.intel.com/intel/legal/tmusage2.htm">http://www.intel.com/intel/legal/tmusage2.htm</a>.

Page 4 of 4 PCN116894-02