



Product Change Notification

Change Notification #: 819816-00

Change Title: Select Intel® Ethernet Controllers and Intel® Ethernet Connections, PCN 819816-00, Transport Media, Update Tape & Reel Intermediate Box IPN A22675-001 with Graphic Artwork, Intel Logo & Barcode

Date of Publication: April 12, 2024

Key Characteristics of the Change:

Transport Media

Forecasted Key Milestones:


Date Customer Must be Ready to Receive Post-Conversion Material	June 28, 2024
--	---------------

Description of Change to the Customer:


Intel will update the Tape & Reel Intermediate Box used in transport of materials, making the following four appearance changes:

1. Adding an IPN barcode for customers to scan
2. Replacing older Intel Logo with newer Intel Logo
3. Updating packaging symbols with new symbols
4. Changing the color of the graphic artwork ink from blue to black

As-Is: IPN A22675-001 Artworks, color (blue)



To Be: IPN A22675-001 Artwork, color (black)



Customer Impact of Change and Recommended Action:

Intel considers this change a MINOR CHANGE. There is no change to the form, fit, functionality, quality or reliability for the products and this notification pertains exclusively to the Intermediate Box listed which is used in the shipment of products.

Customers should notify both their receiving department and any of their Distributing partners, so they are all aware.

Customers will receive a mixture of material boxes used in shipment until older Intermediate Boxes have been fully depleted.

Please contact your Intel Field Representative for any questions or concerns with respect to the change communicated in this Product Change Notification.

Products Affected/Intel Ordering Codes:

Marketing Name	MM#	Product Code	Spec Code
Intel® Ethernet Controller 5 Gigabit V710-AT2, Dual Port, FCBGA,	999WDX	EZV710AT2	S LNGG
Intel® Ethernet Controller 5 Gigabit V710-TM4, Quad Port, FCBGA,T&R	999WF4	EZV710TM4	S LNGJ
Intel® Ethernet Controller I350-AM4, Tape	915808	NHI350AM4	S LJ2Z
Intel® Ethernet Controller E810-CAM1, Tape & Reel	999W9D	EZE810CAM1	S LNFJ
Intel® Ethernet Controller I350-AM2, Tape	915809	NHI350AM2	S LJ3R
Intel® Ethernet Controller 10 Gigabit X710-TM4, Quad Port, FCBGA,T&R	976477	EZX710TM4	S LMM7
Intel® Ethernet Controller X550-AT2, Dual Port, FCBGA, T&R	943743	ELX550AT2	S LL2F
Intel® Ethernet Connection X557-AT2, Dual Port, FCBGA, T&R	941994	EZX557AT2	S LKVY
Intel® Ethernet Controller 10 Gigabit X710-AT2, Dual Port, FCBGA,T&R	980539	EZX710AT2	S LMR6
Intel® Ethernet Controller 10 Gigabit X710-TM4I, FCBGA,T&R	99C56G	EZX710TM4I	S LP9Q
Intel® Ethernet Controller E810-XXVAM2, Tape & Reel	999W9K	EYE810XXVAM2	S LNG2
Intel® Ethernet Connection X557-AT4, Quad Port, FCBGA, T&R	941995	EZX557AT4	S LKW3
Intel® Ethernet Controller E810-CAM2, Tape & Reel	999W9G	EZE810CAM2	S LNFY
Intel® Ethernet Controller 10 Gigabit X710-AT2I, FCBGA, T&R	99AZHX	EZX710AT2I	S LP9N

PCN Revision History:

Date of Revision:

April 12, 2024

Revision Number:

00

Reason:

Originally Published PCN



Product Change Notification

819816-00

Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at www.intc.com.

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apagccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com